

INTERNATIONAL STANDARD

ISO
11095

First edition
1996-02-01

Linear calibration using reference materials

Étalonnage linéaire utilisant des matériaux de référence



Reference number
ISO 11095:1996(E)

Contents

	Page
1 Scope	1
2 Normative references	1
3 Definitions	1
4 General principles	2
5 Basic method	2
6 The steps of the basic method	4
7 Control method	10
8 Two alternatives to the basic method	13
9 Example	16

Annexes

A List of symbols and abbreviations	25
B Basic method when the number of replicates is not constant	27
C Bibliography	29